## Addendum Instruction for all Profile Series - Ribbon Cable Change





Figure 1 - New Ribbon Cable Orientation (install with cable exiting DOWN as shown)

## A7979A

12.20.2007