



ALARM LOCK

345 Bayview Avenue, Amityville, New York, U.S.A. 11701
For Sales and Repairs 1-800-ALA-LOCK • For Technical Service 1-800-645-9440
Fax: 631-789-3383 • info@alarmlock.com

Note: Technical Service is for security professionals only

ALARM LOCK Tech Support

TECH NOTE




Date: Wednesday, July 18, 2012

Subject: Modified Outside Housing Requires New Lever


Models: All Mortise and Exit Trim (except narrow-style) Models

A design modification to the outside housing requires a shorter outside **Lever**, as the existing **Lever** will not fit into the modified outside housing. A new **Spindle Spacer** must also be used.

Therefore, when replacing the outside housing, ensure the new **Spindle Spacer** is fully inserted onto the spindle before attaching the new outside **Lever** (see photo below).



Spindle Spacer **MUST** be placed with "Recess" facing the spindle



New Lever (left); Previous lever (right)

Note: The new **Lever** is NOT interchangeable with previous **Levers**.

If installing a **Lever and Return Spring Upgrade Kit**, see the complete step-by-step instructions detailed in WI2008.