


1931

Cabinet Pull





Side View

Note:

- 1. 1-1/8" Projection from face of the caninet
- 2. Sloped to eliminate ligature points
- 3. Thru-bolted for maximum stabillity