



LHR SHOWN
RHR OPPOSITE

9875/9975 & 9875-F/9975-F Series
Mortise Lock Device (Wood Door)

VON DUPRIN

NOTES: SEE MASTER SHEET #10001 FOR SUGGESTED REINFORCING

TEMPLATE NUMBER:

W10305_a

DATE:
05-29-13

NOTE: MOUNTING HOLES TO BE PREPARED AT INSTALLATION ON DOOR FOR OUTSIDE TRIM PREPARATION, WHEN REQUIRED, SEE ADDITIONAL TRIM TEMPLATE.